DATE: September, 2010

TO: AUTHORIZED portable electric tool SERVICE STATIONS

factory SERVICE / SALES SUPPORT BRANCH

TOOL(S) \ PRODUCT(S) AFFECTED: 2446-20 M12™ Cordless Grease Gun

SUBJECT: adding 44-86-1400 self-locking retaining ring to plunger rod assembly

If not there, it is recommended that a 44-86-1400 self-locking retaining ring be add to the plunger rod assembly when a 2446-20 M12™ Cordless Grease Gun is serviced.

plunger assembly with 44-86-1380 retaining ring



add new 44-86-1400 self-locking retaining ring over existing 44-86-1380 retaining ring with its concave side facing the -1380 retaining ring





This bulletin is for informational purposes. PLEASE NOTE ON SERVICE PARTS LIST: 54-06-2440